


SKEW CLAMP

Skew clamp universal to connect rod to tape or circular conductor. In order to avoid stress corrosion of the clamp, use tape to isolate the clamp from the corrosive environment, i.e. the ground. Stress corrosion occurs in the case of synergy of two factors: the corrosive environment, i.e. the ground, and the constant stress force on the clamp plates caused by the twisted screws. Elimination of the corrosive environment prevents the occurrence of stress corrosion.

Cat. no.	Dimensions		Material
	tape St/Cu mm	wire mm ²	
C1030430N	≤ 40	28-78	stainless steel 2 mm, stainless steel bolts M8



The manufacturer reserves the right to change the product design without prior notice.