


DATA SHEET

SKEW CLAMP

Skew clamp universal, with stainless steel separator, to connect rod to tape or circular conductor. In order to avoid stress corrosion of the clamp, use tape to isolate the clamp from the corrosive environment, i.e. the ground. Stress corrosion occurs in the case of synergy of two factors: the corrosive environment, i.e. the ground, and the constant stress force on the clamp plates caused by the twisted screws. Elimination of the corrosive environment prevents the occurrence of stress corrosion.

Cat. no.	Dimensions			Material
	rod St/Cu mm	tape parallel or squarely to rod mm	wire/cable parallel or squarely to rod mm ²	
C1030428N	14.2; 16	≤ 30	28-78	stainless steel 2 mm, stainless steel bolts M8
C1030429N	17.2	≤ 30	28-78	



The manufacturer reserves the right to change the product design without prior notice.